

Barry Cooper Auto Repairs

82 Federal Street
North Hobart TAS 7000
(04) 5555 5555
ABN 88 009 542 376
Tel: 03 6234 2243 Fax: 03 6234 2482
Email: bcar@eftel.net.au
Website: www.repcoservice.com
After hours 0418882043



Tax Invoice

Invoice No. 34743 **Date** 25/10/23 **Sales ID** Hurd. Zack

Client details

Hui Guo
11 Clearwater Ct
Blackmans Bay 7052 TAS

Vehicule Details

Registration F80UB **ODO** 197658
Make/Model: Toyota Hiace
Year 2017
VIN#: JTFHX02P10011.

JOB DETAILS

Carry out 120month/200,000km service as per handbook
Includes Replaced engine oil & oil filter
Inspected drive belt
Inspected batteryelectrolyte, cleanliness & security
Inspected brake fluid
Checked power steering fluid
Checked condition & pressures of all tyresincluding spare.
Checked lights, wiper/washers, horn, lights & electrical systems
Inspected all seat belts operation & condition
Road tested vehicule & reported any defects.

PARTS

Gasket	1	\$1.95
Oil filter	1	\$28.04

Consumables

Engine oil 5W-30		\$75.00
	Labor	\$85.37
	Miscellaneous	\$20.00

Notes:

Subtotal	\$210.36
GST	\$21.04
Total	\$231.40