Uber Carshare

Owner's Service Form

Inspection		Pass	Fail	Inspection		Pass	Fail
1	BRAKES Right front Right rear	0	000	7	LIGHTS Headlights Turn indicator lights	8	000
	Left front Left rear Handbrake	8	000		Brake lights Tail lights	8	00
2	CLUTCH (manual only)	0	0	9	DOORS (open, close, lock) SPEEDOMETER	д 6	0
3	TYRES Right front Right rear	8	000	10	WARNING LIGHTS	8	0
	Left front Left rear	8	000	11	REAR VIEW MIRRORS SEAT BELTS	<u>ග</u>	0
4	STEERING	0	0	13	AIRBAGS	6	0
5	SUSPENSION Front Rear	8	000				
6	WINDSCREEN Large crack (+3cm)= Fail Small crack (-3cm)= Pass Front glass Front wipers Rear glass Rear wiper (if available	800888	0000000	This car was inspected by the qualified mechanic listed below and satisfactorily passes the checks listed on this form. PASS FAIL			

CAR REGO CISZ FGS.	CARMAKE Toxota	Estima	CAR YEAR 2013	
INSPECTION COMPAN	Lube Mobile		ODO MILEAGE 61726	
INSPECTOR NAME	INSPECTO	DATE OF INSPECTION		
			13-02-24	

Uber Carshare does not inspect car and does not certify the service dates or reliability of a car of information on this form. All forms should be completed by qualified professional mechanics and are only resemble to their opinions.